

Weekly Local Navigation Warning Summary Tuesday 31st Jan 2023

HAURAKI GULF

Hauraki Gulf – The outer starboard hand beacon at the entrance to Puhoi river has been reported as missing.

Waitemata – The Matiatia Bay Approach Directional Light (Dir Oc WRG 6s) Int no. 3845.4 has been reported as showing incorrectly. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Spray Rock isolated danger buoy (FI(2).5s) has been reported missing.

Tamaki Strait – The yellow Special Mark buoy east of Browns Island (FI.Y.5s) has been reported as unlit.

Tamaki River - The North Cardinal Beacon (BY) between Music Point and Browns Island is missing. A replacement is being organised. Mariners are advised to exercise caution when navigating in the area.

Motukorea Channel – The Browns Island North Reef beacon (~~FI.WR.4s~~) Int no. 3847 has been replaced and altered to a North Cardinal (Q.W). Corrections will be issued in due course.

WAITEMATA HARBOUR

Waitemata – The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

MANUKAU HARBOUR

Manukau - The Tokaroa Point starboard beacon (FI.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

Manukau - The Clarks Beach Isolated Danger buoy (FI.(2).4s) has been reported adrift. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Nil