

Weekly Local Navigation Warning Summary Tuesday 20 June 2023

Tamaki River – The Karaka Bay starboard beacon (Fl.G.3s) Int no. 3848.7 has been reported unlit.

Tamaki River – The Tamaki River No.26 Port Hand Beacon has been permanently removed.

Hauraki Gulf – The Takapuna Reef starboard beacon has been reported as destroyed.

Hauraki Gulf – The Weiti River Entrance Starboard beacon (Q.G) Int no. 3741.9 has been destroyed. Mariners are advised to exercise caution when navigating in the area.

Hauraki Gulf – The Weiti River Entrance Port beacon (Q.R) Int no. 3741.92 has been damaged. Mariners are advised to exercise caution when navigating in the area.

Hauraki Gulf – The Orewa river entrance outer starboard beacon has been reported missing.

Hauraki Gulf – The Puhoi River entrance, outer starboard beacon has been reported as missing.

Hauraki Gulf – The Matiatia Bay Approach Directional Light (Dir Oc WRG 6s) Int no. 3845.4 has been reported as showing incorrectly. Mariners are advised to exercise caution when navigating in the area.

Tamaki Strait – The yellow Special Mark buoy east of Browns Island (Fl.Y.5s) has been reported as unlit.

Tamaki River - The North Cardinal Beacon (BY) between Music Point and Browns Island is missing. A replacement is being organised. Mariners are advised to exercise caution when navigating in the area.

WAITEMATA HARBOUR

Waitemata – The Rangitoto Lighthouse Beacon (Fl.R.12s) Int no. 3744 has been reported as unlit.

Waitemata – The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

MANUKAU HARBOUR

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Tamaki River – The Tamaki River No.1 starboard buoy (Q.G) has been reinstated.