



Harbourmaster's Office, Auckland Marine Rescue Centre  
3 Solent Street, Mechanics Bay, Auckland 1010  
Private Bag 92250, Auckland 1142, New Zealand  
+64 9 362 0397 | at.govt.nz

## Weekly Local Navigation Warnings Summary

Tuesday 9<sup>th</sup> June 2026

**Please note that if there are no known changes to Navigation Aid status then there may not be a notice sent out.**

### Waitemata Harbour

-

### Hauraki Gulf

- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. (Cat A, MNZ).

This area has now been surveyed (see attached), mariners are advised to navigate this area with caution until new AtoNs are installed.

### Manukau Harbour

- Nil

### Cancelled Navigation Warnings

---

- Weiti River – The light on the port lateral beacon at the entrance to Weiti River has been reported as not working (Cat ,AT)
- Tamaki River – The light on The port lateral North of Musick point has been serviced.
- Wenderholm – The outer starboard beacon at the river entrance has been reinstated.
- Mahurangi Harbour – The port lateral beacon on Opaheke point has been reinstated.