



Harbourmaster's Office, Auckland Marine Rescue Centre
3 Solent Street, Mechanics Bay, Auckland 1010
Private Bag 92250, Auckland 1142, New Zealand
+64 9 362 0397 | at.govt.nz

Weekly Local Navigation Warnings Summary

Tuesday 20th January 2026

Waitemata Harbour

-

Hauraki Gulf

- Wenderholm – The outer starboard beacon at the river entrance is missing, a temporary buoy has been installed in its place until a new beacon can be installed. (Cat B, AT)
- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. Mariners are advised to navigate this area with extreme caution. (Cat A, MNZ).

Manukau Harbour

- Please be advised that the warning beacon at the entrance to Manukau Heads has been reported as not operating.

Cancelled Navigation Warnings

- Tamaki River – starboard beacon No.23 has been replaced. (Cat B, AT)