

Weekly Local Navigation Warning Summary Tuesday 23 April 2024

Tamaki River – The Tamaki River no.2 beacon (Q.R) Int no. 3849.05 has been reported missing.

Tamaki Strait – East Beach – the east cardinal beacon has been reported missing its top mark. A temporary buoy has been placed alongside.

Hauraki Gulf - The Spray Rock isolated danger buoy (Fl(2).5s) has been reported missing.

WAITEMATA HARBOUR

Waitemata - The West Bastion Reef starboard beacon has reported missing.

Waitemata - The Saltworks Port hand beacon (Coastguard Bay) (Q(3).R.8s) has been reported destroyed. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

MANUKAU HARBOUR

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Nil