



Harbourmaster's Office, Auckland Marine Rescue Centre
3 Solent Street, Mechanics Bay, Auckland 1010
Private Bag 92250, Auckland 1142, New Zealand
+64 9 362 0397 | at.govt.nz

Weekly Local Navigation Warnings Summary

Tuesday 2nd December 2025

Waitemata Harbour

-

Hauraki Gulf

- Spray Rock – Isolated danger beacon top mark and light are missing. (FL(2)5s4m2M). (Cat , AT)

Manukau Harbour

- Please be advised that the warning beacon at the entrance to Manukau Heads has been reported as not operating.

Cancelled Navigation Warnings

- Northcote Mooring area - SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36°49.60S 174°45.33E. Has now been repositioned.
- Karaka Point – The isolated danger buoy has been reported as out of position. Has been repositioned.