



Harbourmaster's Office, Auckland Marine Rescue Centre  
3 Solent Street, Mechanics Bay, Auckland 1010  
Private Bag 92250, Auckland 1142, New Zealand  
+64 9 362 0397 | at.govt.nz

## Weekly Local Navigation Warnings Summary

Tuesday 30<sup>rd</sup> June 2026

Please note that if there are no known changes to Navigation Aid status then there may not be a notice sent out.

### Waitemata Harbour

#### Hauraki Gulf

- Motuihe Channel, the light on No.1 Starboard buoy has been reported as not working. (Cat A, POAL)
- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. (Cat A, MNZ).

This area has now been surveyed (see attached), mariners are advised to navigate this area with caution until new AtoNs are installed.

#### Manukau Harbour

- Nil

#### Cancelled Navigation Warnings

---

- Bayswater Marina, No.6 Port beacon at entrance to Bayswater marina has been replaced. (Cat A, Bays Water Marina).