



Harbourmaster's Office, Auckland Marine Rescue Centre
3 Solent Street, Mechanics Bay, Auckland 1010
Private Bag 92250, Auckland 1142, New Zealand
+64 9 362 0397 | at.govt.nz

Weekly Local Navigation Warnings Summary

Tuesday 6th January 2026

Waitemata Harbour

-

Hauraki Gulf

- Spray Rock – Isolated danger beacon top mark and light are missing. (FL(2)5s4m2M). (Cat , AT)
- Tamaki River – starboard beacon No.23 is damaged and will be removed, a temporary buoy will be in its place until a replacement beacon can be installed. (cat B, AT)
- Motuihe Channel – The southern most Transit Lane special mark has been damaged. (Cat A, AT)
- Wenderholm – The outer starboard beacon at the river entrance has been reported as missing, a temporary buoy will be in its place until a new beacon can be installed. (Cat B, AT)

Manukau Harbour

- Please be advised that the warning beacon at the entrance to Manukau Heads has been reported as not operating.

Cancelled Navigation Warnings
