



Harbourmaster's Office, Auckland Marine Rescue Centre
3 Solent Street, Mechanics Bay, Auckland 1010
Private Bag 92250, Auckland 1142, New Zealand
+64 9 362 0397 | at.govt.nz

Weekly Local Navigation Warning Summary Monday 11 August 2025

Great Barrier Island

Man of War Passage - The Paget Rock Isolated Danger Marker (Fl(2).W.4s) has been reported as broken off from the original position.

Whangaparaoa

Whangaparaoa – The Gulf Harbour Marina approach sector light (Fl.WR.3s) Int no. 3741.5 has been reported as unlit.

MAHURANGI HARBOUR

Mahurangi – The Port buoy (Fl.R.2s) marking the reef North of Saddle Island/ Te Haupa has been reported as unlit.

HAURAKI GULF

Castor Bay – Rahopara Point starboard beacon (Fl.G.5s) Int no. 3743.2 has been reported missing.

WAITEMATA HARBOUR

Waitemata – The Iliomama light (Q.WR.2m5/3M) Int no. 3847.5 has been reported as unlit.

Waitemata – The Browns Island North Cardinal beacon (Q.6m.4M) Int. no. 3847 has been reported as unlit.

Waitemata – The Rough Rock buoy (Q(3).10s) has been reported as dim.

Waitemata – The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36°49.60S 174°45.33E. Final position will be advised in due course.

TAMAKI RIVER

Tamaki River - The no.9 Starboard channel marker light (Fl(2).G.3s) has been reported as dim.

MANUKAU HARBOUR

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

Manukau - The Matakawau Point starboard beacon (Fl.G.2s) Int no. 4110.05 has been reported as destroyed. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Nil