

## **Weekly Local Navigation Warning Summary Monday 17 February 2025**

Whangaparaoa - The Gulf Harbour Marina approach sector light (Fl.WR.3s) int no.3741.5 has been reported as unlit.

### **WAITEMATA HARBOUR**

Waitemata - The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

### **MANUKAU HARBOUR**

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

### **CANCELLED NAVIGATION WARNINGS**

Manukau - The Wairopa Channel no.5 starboard beacon (Q(4).G.6s) int no 4116.25 has been reported as repaired.

Manukau - The Wairopa Channel no.17 starboard beacon (Fl(2).G.5s) int no 4116.45 has been reported as repaired.

Manukau - The Wairopa Channel no.21 starboard beacon (Oc.G.6s) int no 4116.75 has been reported as repaired.