Harbourmaster's Office, Auckland Marine Rescue Centre
3 Solent Street, Mechanics Bay, Auckland 1010
Private Bag 92250, Auckland 1142, New Zealand
+64 9 362 0397 | at.govt.nz

Local Navigation Warnings Summary

Tuesday 29th September 2026

Please note that if there are no known changes to Navigation Aid status then there may not be a notice sent out.

Waitemata Harbour

- Nil

Hauraki Gulf

- Motuihe Channel, the light on No.1 Starboard buoy has been reported as not working, this is currently being worked on and will be remedied when the buoy is replaced. (Cat A,POAL)
- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. (Cat A, MNZ).

  This area has now been surveyed (see attached), mariners are advised to navigate this area with caution, new AtoN configuration to be installed soon.

Manukau Harbour

- Nil

Cancelled Navigation Warnings

- Upper Harbour, Special mark "Meola racing buoy A" has been permanently relocated to approximately 150m ENE of its charted position.
- Motukorea Channel, Special mark "Iliomama harbour racing buoy" has been permanently relocated to approximately 2.5NM ENE of its charted position and now sits out side of Islington Bay.

Auckland Transport