Local Navigation Notices

Current as of 3rd November 2026

Waitemata Harbour

- Nil

Hauraki Gulf

- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. (Cat A, MNZ).

  This area has now been surveyed (see attached), mariners are advised to navigate this area with caution, new AtoN configuration to be installed soon.

Manukau Harbour

- Nil

Resolved Navigation Notices

- Motuihe Channel, the light on No.1 Starboard buoy has been replaced, along with the buoy. (Cat A, POAL)