Local Navigation Notices

Current as of 24th November 2026

Waitemata Harbour

- Nil

Hauraki Gulf

- The North Cardinal on the reef off the eastern end of Algies Bay is missing, there has been a temporary buoy installed while a replacement beacon is worked on.

  36 25.870S 174 45.601E (Cat A, AC).

- The drying bank to the south of Karamuramu Island (Kawakawa Bay) - Due to the severe shoaling (as per Local Notice to Mariners 19-25) the South Cardinal has been temporarily changed to show as a special mark beacon. (Cat A, MNZ).

  This area has now been surveyed (see attached), mariners are advised to navigate this area with caution, new AtoN configuration to be installed soon.

Manukau Harbour

- Nil

Resolved Navigation Notices

-