

## **Weekly Local Navigation Warning Summary Monday 8 July 2024**

Kawau Bay – The beacon between Algies Bay and Goldsworthy Bay has been reported as missing.

Great Barrier Island – The Paget Rock isolated danger buoy (Fl(2).4s) has been reported missing.

Hauraki Gulf - The Spray Rock isolated danger buoy (Fl(2).5s) has been replaced with a lit beacon. Notice to Mariners will be issued in due course.

### **WAITEMATA HARBOUR**

Waitemata - The Bayswater no.1 starboard beacon (Fl.G.3s) int no 3770.01 has been reported missing. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Whau River no.6 lit beacon (Q.R) int no. 3837.1 has been reported as missing. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Saltworks Port hand beacon (Coastguard Bay) (Q(3).R.8s) has been reported destroyed. Mariners are advised to exercise caution when navigating in the area.

Waitemata - The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

### **MANUKAU HARBOUR**

Manukau - The Tokaroa Point starboard beacon (Fl.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

### **CANCELLED NAVIGATION WARNINGS**

*Waitemata - The Rangitoto Channel no.7 buoy (ISO.G.1s) has been repaired.*