

Weekly Local Navigation Warning Summary Monday 20 January 2025

WAITEMATA HARBOUR

Waitemata – A starboard lateral marker by Browns Island has been reported unlit. No further details have been supplied.

Waitemata – A starboard lateral marker has been reported floating off Cheltenham Beach. No further details have been supplied.

Waitemata - The Northcote Mooring area SE Port hand beacon in charted position 36° 49.64S 174° 45.37E has been temporarily positioned at 36° 49.60S 174°45.33E. Final position will be advised in due course.

MANUKAU HARBOUR

Manukau - The Wairopa Channel no.5 starboard beacon (Q(4).G.6s) int no 4116.25 has been reported as unlit.

Manukau - The Wairopa Channel no.17 starboard beacon (FI(2).G.5s) int no 4116.45 has been reported as unlit.

Manukau - The Wairopa Channel no.21 starboard beacon (Oc.G.6s) int no 4116.75 has been reported as unlit.

Manukau - The Tokaroa Point starboard beacon (FI.G.4s) Int no. 4110.07 has been reported as destroyed. A temporary green buoy is reported to be in its place. Mariners are advised to navigate with caution in the area.

CANCELLED NAVIGATION WARNINGS

Waitemata - The Whau River no.6 lit beacon (Q.R) int no. 3837.1 has been reported as reinstated.