

Final Decisions by Treatment/Location

Balmoral North (north to south, east to west)

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
Sandringham Road/Ward Terrace Intersection	Threshold Treatment	No Change	Threshold Treatment
54 King Edward Street	Slow Markings	No Change	Slow Markings
2 King Edward Street	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Paice Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
83 Paice Avenue	No Treatment	NEW – ‘Road Narrowing’ removed from 75 Paice Avenue and replaced with ‘Slow Markings’ outside 83 Paice Avenue.	Slow Markings
75 Paice Avenue	Road Narrowing	REPLACED – ‘Road Narrowing’ removed from 75 Paice Avenue and replaced with ‘Slow Markings’ outside 83 Paice Avenue.	No Treatment
41 Paice Avenue	Speed Hump	No Change	Speed Hump
27 Paice Avenue	Speed Hump	No Change	Speed Hump
15 Paice Avenue	Speed Hump	No Change	Speed Hump
1 Paice Avenue	Speed Hump	No Change	Speed Hump
Dominion Road/Paice Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Gribblehurst Road Intersection	Threshold Treatment	No Change	Threshold Treatment
78 Gribblehurst Road	Speed Hump	No Change	Speed Hump
65 Gribblehurst Road	Speed Hump	No Change	Speed Hump
57 Gribblehurst Road	Speed Hump	No Change	Speed Hump
47 Elizabeth Street	Speed Hump	No Change	Speed Hump
25 Elizabeth Street	Speed Hump	No Change	Speed Hump
9 Elizabeth Street	Speed Hump	No Change	Speed Hump

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
Dominion Road/Elizabeth Street	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Parrish Road Intersection	Threshold Treatment	No Change	Threshold Treatment
14 Parrish Road	Speed Hump	No Change	Speed Hump
29 Parrish Road	Speed Hump	No Change	Speed Hump
40 Parrish Road	Speed Hump	No Change	Speed Hump
50 St Albans Avenue	Speed Hump	REPLACED – ‘Raised Table Pedestrian Crossing’ to replace former ‘Speed Hump’. Pedestrian crossing to be similar to Brixton Road pedestrian facility with kerb build outs (no zebra crossing to be provided).	Raised Table Pedestrian Crossing
39 St Albans Avenue	Raised Pedestrian Crossing	REPLACED – ‘Speed Hump’ to replace former ‘Raised Pedestrian Crossing’ (due to revised treatment at 50 St Albans Avenue)	Speed Hump
28 St Albans Avenue	Speed Hump	No Change	Speed Hump
11 St Albans Avenue	Speed Hump	No Change	Speed Hump
Dominion Road/St Albans Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Cambourne Road Intersection	Threshold Treatment	No Change	Threshold Treatment
11 Cambourne Road	Slow Marking	REPLACED – ‘Speed Hump’ to replace former ‘Slow Marking’	Speed Hump
33 Goring Road	Slow Marking	REPLACED – ‘Speed Hump’ to replace former ‘Slow Marking’	Speed Hump
Sandringham Road/Truro Road Intersection	Threshold Treatment	No Change	Threshold Treatment
18 Truro Road	Slow Marking	No Change	Slow Marking
16 Goring Road	Slow Marking	REPLACED – ‘Speed Hump’ to replace former ‘Slow Markings’	Speed Hump
Dominion Road/Brixton Road Intersection	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Lancing Road Intersection	Threshold Treatment	No Change	Threshold Treatment

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
15 Lancing Road	Slow Marking	No Change	Slow Marking
6 Goring Road	No Treatment	NEW – ‘Slow Marking’ added to this location	Slow Marking
23 Dunbar Road	Slow Marking	No Change	Slow Marking
9 Dunbar Road	Threshold Treatment	No Change	Threshold Treatment
Balmoral Road/Goring Road Intersection	Threshold Treatment	No Change	Threshold Treatment

Balmoral South (north to south, east to west)

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
Balmoral Road/Arabi Street Intersection	Threshold Treatment	No Change	Threshold Treatment
Balmoral Road/Volcanic Street Intersection	Threshold Treatment	No Change	Threshold Treatment
4 Arabi Street	Slow Marking	No Change	Slow Marking
27 Wiremu Street	Speed Hump	No Change	Speed Hump
11 Wiremu Street	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Patterson Street Intersection	Threshold Treatment	No Change	Threshold Treatment
13 Patterson Street	Slow Marking	No Change	Slow Marking
7 Volcanic Street	Slow Marking	No Change	Slow Marking
Sandringham Road/Jason Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
14 Jason Avenue	Slow Marking	No Change	Slow Marking
15 Tennyson Street	Slow Marking	No Change	Slow Marking
1 Tennyson Street	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Mars Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
12 Mars Avenue	Slow Marking	No Change	Slow Marking
44 Arabi Street	Speed Hump	No Change	Speed Hump
2A Carmen Avenue	Threshold Treatment	No Change	Threshold Treatment

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
Sandringham Road/Oxton Road Intersection	Threshold Treatment	No Change	Threshold Treatment
14 Oxton Road	Slow Marking	No Change	Slow Marking
Arabi Street/Oxton Road Intersection	No Treatment	NEW – improve paint markings and sign visibility at intersection.	Paint Road Markings and improve Sign Visibility
50 Arabi Street	No Treatment	NEW – ‘Speed Hump’ based on AT Road Operations request	Speed Hump
Dominion Road/Telford Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Tranmere Road Intersection	Threshold Treatment	No Change	Threshold Treatment
14 Tranmere Road Intersection	Slow Marking	No Change	Slow Marking
Arabi Street/Halesowen Avenue Intersection	No Treatment	NEW – improve paint markings and sign visibility at intersection	Paint Road Markings and improve Sign Visibility
Arabi Street midway between Oxton Road and Tranmere Road	No Treatment	NEW – ‘Speed Hump’ based on AT Road Operations request	Speed Hump
Sandringham Road/Halesowen Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
14 Halesowen Avenue	Speed Hump	No Change	Speed Hump
52 Halesowen Avenue	Speed Hump	‘Speed Hump’ was delivered as part of the Dominion Road Parallel Cycle Route	No Treatment
66 Halesowen Avenue	Road Narrowing	REMOVED – ‘Road Narrowing’ removed from 66 Halesowen Avenue	No Treatment
82 Halesowen Avenue	Speed Hump	No Change	Speed Hump
Dominion Road/Halesowen Avenue Intersection	Threshold Treatment	No Change	Threshold Treatment
3 Calgary Street	Threshold Treatment	No Change	Threshold Treatment
16 Calgary Street	Speed Hump	No Change	Speed Hump
50 Calgary Street	Road Narrowing	REPLACED – ‘Speed Hump’ to replace former ‘Road Narrowing’	Speed Hump
64 Calgary Street	Speed Hump	No Change	Speed Hump

Address / Location	Traffic calming measure proposed during consultation	Comments / final treatment	Final traffic calming measure
82 Calgary Street	Speed Hump	No Change	Speed Hump
98 Calgary Street	Speed Hump	No Change	Speed Hump
Dominion Road/Calgary Street Intersection	Threshold Treatment	No Change	Threshold Treatment
15 Wembley Road	No Treatment	NEW – ‘Slow Marking’	Slow Marking
Dominion Road/Wembley Road Intersection	Threshold Treatment	No Change	Threshold Treatment
Sandringham Road/Lambeth Road Intersection	Threshold Treatment	No Change	Threshold Treatment
85 Lambeth Road	Speed Hump	No Change	Speed Hump
41 Lambeth Road	Speed Hump	No Change	Speed Hump
Lambeth Road/Highcliffe Road Intersection	Raised Junction	No Change	Raised Junction
15 Lambeth Road	Speed Hump	No Change	Speed Hump
Dominion Road/Lambeth Road	Threshold Treatment	No Change	Threshold Treatment