



Western Approach



Legend

-  Existing Broken Yellow Lines
-  Broken Yellow Lines to be Repainted
-  Existing Centreline
-  Old Centreline
-  New Centreline

NOT TO SCALE
Photographs might not reflect recent changes.


Page 1 of 3
Date: 28/03/2022

Tainui Road, Saint Johns
Broken Yellow Lines and Centreline Shift

Prepared by:
David Boulton
Auckland Transport
(TE Central)



Eastern Approach



Legend

-  Existing Broken Yellow Lines
-  Existing Centreline
-  Old Centreline
-  New Centreline

NOT TO SCALE
Photographs might not reflect recent changes.

Page 2 of 3
Date: 28/03/2022

Tainui Road, Saint Johns Broken Yellow Lines and Centreline Shift

Prepared by:
David Boulton
Auckland Transport
(TE Central)





Overview Location

NOT TO SCALE

Photographs might not reflect recent changes.

Page 3 of 3

Date: 28/03/2022

Tainui Road, Saint Johns

Broken Yellow Lines and Centreline Shift

Prepared by:
David Boulton
Auckland Transport
(TE Central)

